### (b) Last of Mines at which Permitted Explosives are used.

The following is a list of mines as at the 31st December, 1939, at which permitted explosives are used:--

### Northern Inspection District.

Pukemiro, Pukemiro - Throughout North and South Mines.

Rotowaro, Rotowaro—Throughout No. 1 and No. 3 Mines.

Glen Afton, Glen Afton -All sections of the mine.

MacDonald, Waikokowai-Throughout all sections of the mine.

Waikato Extended Colliery, Huntly—All sections.

Renown, Renown—All sections.

Wilton, Glen Massey—All sections.

### West Coast Inspection District.

Wynndale, Murchison.

Puponga, Puponga.

Owen, Owen River.

Brighton, Brighton.

Charming Creek, Ngakawau.

Cascade, Burnett's Face.

Coal Creek, Seddonville.

Hydro, Seddonville.

Glenerag, Buller Gorge.

Westport Coal Co.'s Denniston mines.

Westport Coal Co.'s Millerton mines.

Westport-Stockton, Ngakawau.

Archer's, Capleston.

Clele, Merrijigs.

Coghlan's, Capleston.

Morrisvale, Reefton.

Defiance, Reefton.

Burke's Creek, Reefton.

Waitahu Colliery, Reefton.

Burnwell (Honey's), (Times Street), Reefton.

Schultz Creek, Twelve Mile.

Hilltop, Ten Mile. Kaye's, Ten Mile.

Bellbird, Ten Mile.

Hunter's, Ten Mile.

Briandale, Ten Mile.

Cliffside (Moore's), Nine Mile.

Bellvue, Rapahoe.

Cain's, Rapahoe.

Jubilee, Rapahoe.

Baddeley's, Dunollie. Brachead, Dunollie.

Castlepoint, Dunollie. Hunter's, Rewanui.

Moody Creek, Dunollie.

New Point Elizabeth, Dunollie.

Fiery Cross, Dunollie.

Smith's, Dunollie.

Old Runanga, Rewanui.

Spark's, Rewanui.

State Colleries (Liverpool), James, and Strong-

man).

Goldlight, Rewanui.

Blackball, Blackball.

Blackball Creek, Blackball.

Paparoa, Roa.

Dobson, Dobson.

Wallsend, Brunnerton.

Westhaven, Mangarakan.

McCaffrey's, Reefton.

### Southern Inspection District.

Kaitangata, Kaitangata.

Wairaki, Ohai.

Birchwood, Ohai.

Linton, Ohai.

Jubilee, Saddle Hill.

East Taieri, East Taieri.

Black Diamond, Ohai. Black Lion, Ohai.

Star, Ohai.

Fernhill, Abbotsford.

Willowbank, East Taieri.

### (c) List of Mines required by Law to use Safety-lamps.

The following is a list of the mines as at the 31st December, 1939, required by law to use safety-lamps.

# Northern Inspection District.

Pukemiro, Pukemiro - Throughout South Mine Section.

Rotowaro, Rotowaro - Throughout No. 1 and No. 3 Mines.

Glen Afton, Glen Afton Main headings.

Renown, Renown—Nos. 1, 2, 3, and 4 North Sections.

### West Coast Inspection District.

Dobson, Dobson.

Spark's, Rewanui.

State Mine (Liverpool No. 2), Rewanui.

Moody Creek, Dunollie.

Old Runanga (Nos. 1 and 2 Sections), Rewanui.

Kaye's, Ten Mile.

Paparoa, Roa.

Wallsend, Brunnerton.

Millerton (Old Dip Section), Millerton.

Owen, Owen River.

Strongman, Nine Mile.

Wynndale, Murchison.

Hunter's, Rewanui. Bellbird, Ten Mile.

## Southern Inspection District.

Kaitangata, Kaitangata.

Wairaki, Ohai. Birchwood, Ohai. Linton, Ohai.

Black Diamond, Ohai. Black Lion, Ohai. Star, Ohai.