## Our 41st. Competition


Won By G. W. HAINES ("XXX,") Christelarch


Only two designs were sent in for this competition viz.:- "April Morn" by N. Wallnutt with Messes. Mahoney & Son, Auckland, and "XXX" by G. W. Haines with Mr. J. S. Guthrie, of Christehurch. The judge, Mr. Wm. II. Dunning of Dunedin reports as follows:—


"This competition was the means of bringing out only two competitors, which is very disappointing as etc. Enough attention has not been given to lighting, the light arears being far too small. By extending them it would have made the strong room, cleak room and back entrance in better proportion and have given the necessary light. The first floor is well arranged with the exception that the passage leading across area is backy lighted, but could be easily overcome. The elecations are well drawn though somewhat domestic in treatment. It is a pity a little more of the halfhad detail of fittings was not shown, also more attention paid to the drawing of these,
"APRIL MORN" has a well drafted set of

drawings, although his not took Csetting the building back from the boundaries on both sides does not give










CECUID Tiens He



FLOOR FLAN -



Winning design "XXX," by G. W. Halines with Mr. J. S. Guthrie of Christehurch

it is a subject which should call for good competition. After carefully considering the two sets of drawings, I would place them in the following orders  $\langle \forall XXX \rangle$ and "April Morn."

" $X\hat{X}X$ " has shown a good deaf of originality in his planning, but has failed to grasp the problem in The Banking Chamber is well many points. arranged, but the Manager's room is far too small and would require access to the staff, as having to cross the public space is not desirable. This could have been obtained by making the side wall in the shape of a bay carried out in wood to harmonize with the fittings; the other side of entrance being treated in a similar way and fitted with a table for writing cheques

the best result as it necessitate, the majority of light being obtained frem leng narrow right-of-ways. The Banking Chamber, though spacious, would not be well lighted at the back, although the manager's room, strong mean, and invatories, are well arranged. private entrance should have been nearer the front, and cotside back entrance brought in under cover. The central corridor on first floor is badly lighted, and the same thing applies to all rooms opening on to right-of-ways. The elevation has been carefully done and would look well in execution. The half inch detail drawings of fittings have also been well thought out."