



TRANSVERSE SECTION OF NAVE

Notice the great depth of abutment to the Nave vaulting, precluding any possibility of "thrust."