Sept. 28	Excelsior aux. schnr., 28 years	Schooner	6	3	..	..	Collision	..	Auckland Harbour ..	..	..	When the "Excelsior" was going down the harbour a launch collided with her broadside on, striking her abaft the forward rigging, but doing no damage	J. Clark.
" 28	Name unknown, launch	..	..	..	..	..							
" 29	Katoa, s.s., 12 years	F. and A.	1,271	34	..	900 tons telegraph poles	Steam-valve chamber cracked	..	Auckland Harbour ..	..	..	When port boiler auxiliary valve was being opened up to pump up boiler a crack developed in valve chamber of starboard boiler	D. Ritchie.
Oct. 8	Mahurangi, s.s., 16 years	Schooner	95	11	..	160 tons cement	Touched bottom, damaging vessel's stern	..	Auckland Harbour ..	N.W.	Light ..	When proceeding to wharf, the tide being very low, the vessel took the bottom, and, finding she would not steer, the master ordered "Full speed astern," resulting in vessel hitting the wharf and carrying away part of her stern.	F. Savage.
" 10	Kaimanawa, s.s., 15 years	F. and A.	1,247	31	..	3,000 tons coal	Leaking boiler; £50 damage	..	Newcastle, New South Wales	..	..	The chief engineer reported that a boiler was leaking (which he temporarily repaired) and that vessel was fit to proceed on voyage, on which no further trouble occurred	A. B. Sizer.
" 11	Dauntless, o.e.v., 15 years	F. and A. Launch	3	2	..	..	Collision	..	Nelson Street Wharf, Auckland	N.W.	3	When the "Dauntless" was going alongside the wharf the engine stalled and vessel collided with the stern of the "Fox," which was moored at wharf, doing £10 damage	Alex. Cole.
" 11	Fox, o.e.v., fishing launch (age not known)	Lugger..	4	2	..								A. Polecondriotis.
" 17	Coronation, aux., 16 years	Schooner	59	6	..	General, 120 tons	Stranded.. ..	..	Parenga Harbour ..	S.W.	Gale ..	Vessel went for shelter, but owing to narrow channel was not able to give much cable, resulting in vessel dragging her anchor and resting on mud-bank, from which she was refloated, no damage having been done to herself or cargo	H. Anderson.
" 19	Elsie, o.e.v., 21 years	Ketch ..	24	4	3	General foodstuffs, 15 tons	Stranded ..	..	Jackson's Bay ..	W.	3	Vessel ran for shelter, but, owing to lack of engine-power and to anchor not holding, vessel began to drift inshore, where master beached her, enabling crew and passengers to walk ashore	A. G. Ingram.
" 24	Isabella de Fraine, o.e.v., 22 years	Schooner	76	7	..	81,000 ft. timber	Fore-top-mast, &c., carried away; £250 damage	..	South Cape Brett ..	W.S.W.	Moderate	The screw on bobstay carried away, causing bowsprit to snap off at gammoning-band, bringing down foretopmast, all of which resulted from bad weather encountered on west coast	J. D. Bell.
" 25	Ruapehu, s.s., 24 years	F. and A.	5,797	127	359	General ..	Leaking valve in steam-pipe	..	Mersey River ..	S.E.	3	A heavy leakage was found in the flange of auxiliary steam-pipe of the starboard boiler, which was repaired on arrival at Auckland	A. W. McKeller.
" 29	Opihi, s.s., 38 years	F. and A.	674	25	..	961 tons ..	Damaged plate in bow	..	Wellington Harbour ..	N.W.	7–8	When approaching wharf, starboard bow of vessel came in contact with wharf, cracking and holeing one plate in bow	W. H. D. Gardiner.
" 31	Zita, aux., 46 years	F. and A.	73	8	..	Timber ..	Touched bar ..	..	Hokianga Bar ..	N.E.	Moderate	When proceeding over bar, outward bound, master altered course to south, as directed by semaphore signals, and continued southwest after arm dropped, but touched bar several times	J. Francis.
Nov. 9	Port Melbourne, s.s., 11 years	F. and A.	5,852	104	11	General, 11,000 tons	Meat door No. 2 'tween deck injured	..	Liverpool Dock, England	..	..	When ship passing from Cumister Dock to Sandon on currents, and when scraping along, pressed against meat-door on No. 2 'tween deck, and although apparently no damaged done, yet thirty-eight days out she began to leak, and on arrival at Auckland repairs were effected	F. J. Kearney.