RETURN of NOTICES given to REPAIR BOILERS in the OTAGO DISTRICT during the Financial Year ended the 31st March, 1890.

	Locomotive Vertical Longitudinal tubular Longitudinal tubular Vertical Portable Vertical Cornish Vertical	Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Locomotive Vertical Longitudinal tubular Longitudinal tubular Vertical Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Retubed.  New fire-box and uptake.  One new plate put in at blow-off cock.  Plate indented taken out and made good.  To be repaired at bottom of shell.  Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Locomotive Vertical Longitudinal tubular Longitudinal tubular Vertical Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Retubed.  New fire-box and uptake.  One new plate put in at blow-off cock.  Plate indented taken out and made good.  To be repaired at bottom of shell.  Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Vertical Longitudinal tubular Longitudinal tubular Vertical Portable Cornish Vertical Semi-portable Locomotive Longitudinal tubular	New fire-box and uptake.  One new plate put in at blow-off cock.  Plate indented taken out and made good.  To be repaired at bottom of shell.  Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Longitudinal tubular Longitudinal tubular Vertical Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	One new plate put in at blow-off cock.  Plate indented taken out and made good.  To be repaired at bottom of shell.  Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Longitudinal tubular Vertical Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Plate indented taken out and made good. To be repaired at bottom of shell. Two longitudinal stays to be put in. Cylinder to be taken off and rejointed. Plate in crown of furnace to be cut out and renewed. Mudholes to be repaired. Fire-box to be patched at bottom and a number of screwed New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Vertical Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	To be repaired at bottom of shell.  Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Portable Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Two longitudinal stays to be put in.  Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Vertical Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Cylinder to be taken off and rejointed.  Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed.  New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Cornish Vertical Semi-portable Locomotive Longitudinal tubular	Plate in crown of furnace to be cut out and renewed.  Mudholes to be repaired.  Fire-box to be patched at bottom and a number of screwed New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Vertical Semi-portable Locomotive Longitudinal tubular	Fire-box to be patched at bottom and a number of screwer New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Locomotive Longitudinal tubular	Fire-box to be patched at bottom and a number of screwer New steam-pipes.  [stays put in Seams on top of shell to be caulked.
	Locomotive Longitudinal tubular	New steam-pipes. [stays put in Seams on top of shell to be caulked.
	Longitudinal tubular Vertical	
	Vertical	
	A OT ATOMY	Plate to be put on at bottom of shell.
	Cornish tubular	To be retubed.
	Portable:	Mudholes to be repaired.
	Portable	Fusible-plug and patch on crown.
	Locomotive	Eight screwed stays to be renewed and mudhole patched.
	${f Portable}  \dots  {f}^{!}$	Outer fire-box to be partly sheathed.
		At corner and mudholes repaired, part of crown-seams to be rerivetted.
	Portable	Two extra dog-stays to be fitted on crown of fire-box, and compensation-ring put round manhole.
	Portable	A number of screwed stays to be renewed in fire-box.
	Lancashire	Furnaces corroding, two small plates to be cut out and renewed, and also three others small.
1	Semi-portable	Condemned.
	•••	Portable Locomotive Portable Semi-portable Portable Portable Lancashire

Return of Notices given to fence Dangerous Parts of Machinery in the Otago District during the Financial Year ended the 31st March, 1890.

Date of Notice.	Class of Machinery,	Parts requiring to be fenced.
Nil	Nil	Nil.

RETURN of Accidents to Life and Limb which have occurred in connection with Land Boilers and Machinery in the Otago District during the Financial Year ended the 31st March, 1890.

Name and Address of Owner.	Description of Machinery.	Name of Person injured.	Nature of Accident.	Fatal or not.	Cause of Accident, and Remarks.
M. Donaghy and Co., So' Dunedin, 31st July, 1889	Rope-spin- ing ma- chinery, known as drawing- inachine	Edward E d- wards, aged 14 years last May	torn off at		The boy at work stands in front of the machine where the fibre comes out and coils into his tub; this place he has no business to leave without first stopping his machine, but, as the lad states himself, he saw something requiring to be taken out, for this purpose he went round the side of the machine and put his right hand underneath the endless-chain belt, when his arm was caught and torn off at the elbow. It was amputated above the elbow. I called at the works on the 1st August, but could offer no suggestions for future prevention.