

Feb.	7	Trusty, 27 years	Schooner	59	3	..	Ballast..	Collision; partial loss	..	Two miles in a direct line from entrance to Inner Harbour, Napier	S.E.	Light ..	Vessel was proceeding alongside s.s. "Manapouri," then lying in roadstead, to lighter her, when the wind shifted, and the steamer swinging caused the "Trusty" to come into collision with her	Edward Quinlan.
"	10	Mana, s.s., 5 years	Cutter ..	51	..	..	..	Fire on board; partial loss	..	Alongside Jervois Quay, Wellington Harbour	..	..	Fire was probably drawn on stokehole-floor and not properly extinguished	James Jones.
"	24	Mamari, s.s., 2 years	Schooner	2349	52	..	Frozen meat, wool	Collision with wharf-piling; partial loss	..	Sumpter Wharf, Oamaru Harbour	S.E.	Light ..	Heavy range coming into harbour, result of a gale in the far offing, caused vessel to surge heavily about, and coming into contact with wharf-piles dented several plates	Joseph Maxwell.
Mar.	11	Charles Edward, s.s., 27 years	Schooner	140	..	..	General	Collision; no damage	1	Inner Harbour, Nelson	..	..	Casualty caused by whistle of steamer not being blown when going down harbour as required by regulations, and in steamer not giving way to sailing-vessel. Master and mate of steamer ordered to pay cost of inquiry	Thomas White-well.
"	18	Ida ..	Cutter ..	10	3	..	Coal	Collision; partial loss			..	..		Cockram West-rupp.
"	18	Mawhera, s.s., 7 years	Schooner	340	26	20	General	Stranded; loss of propeller-blades; partial loss	..	Entrance Ledge, Nelson Harbour	..	Calm ..	Vessel struck on N.E. edge of entrance ledge when leaving port in charge of pilot, and stripped blades off propeller	Walter Manning.
"	19	Compadre, 23 years, A1 Lloyd's	Barque..	800	16	..	Jute-bags	Fire on board and stranded; total loss	1	North Cape, Auckland Islands	N.W.	Storm ..	Fire broke out amongst cargo, and master then shaped his course for New Zealand, but, having met with very bad weather, which carried away some sails and made the vessel waterlogged, she was unable to clear the Auckland Islands, and had to be run ashore to save life. As soon as she struck, the crew jumped ashore off the jibboom, and the vessel then fell back and went to pieces. No blame attached to master or officers	David Jones.