WORKING DREDGES INSPECTED—continued.

Name of Dredge and Locality.	Очрета.	Dredgemaster.	Remarks.	Dates of Visits.
CLUTHA RIVER—continued. Cool Creek to Alexandra Gorne—ctd				
*New Bendigo	New Bendigo Gold-dredging Company	W. Woodhouse P. McVicar	Dredge being shifted to new claim; life-saving appliances in fair order Dredge idle owing to high river Main-engine fly-wheel to be guarded, and gangway hand-rail required; new copy of regulations	3/4/03 13/5/03 21/9/03
*New First Chance	New First Chance Gold-dredging Company		to be posted up Ladder has been lengthened 9 fb,, and pontoons lengthened to carry extra weight; suitable 12 in. by 12 in. blue-gum ladder-bearer ordered; dredge and life-saving appliances in good	19/2/08
	•		Dredge being fitted with false bows; life-saving appliances in fair order Dredge and life-saving appliances in first-class order	3/4/03 13/5/03
*Sailor's Bend	Sailor's Bend Gold-dredging Company	J. Dewar	Engaged lowering pivot-shaft of ladder; suitable 12 in, by 12 in. blue-gum ladder-bearer ordered; dreege and life-saving appliances in first-class order.	21/9/03 19/2/03
			Trende and the saving applicances in good order.	21/9/03 21/9/03
*Manuherikia	Manuherikia Gold-dredging Company	L. Anderson	Dredge has been fitted with false bows to carry weight of extended ladder; life-saving appliances in good order	19/2/03
*Moa No. 1	Clyde Gold-dredging Company	W. Nicholson	Dredge and life-saving appliances in good order; new copy of regulations to be posted up Securely moored on the Manuherikia River	21/9/03 19/2/03
*Moa No. 2	:		Deing dismanded Guard-rail on fly-wheel of main engine to be replaced; otherwise dredge and life-saving appli- ances in good order	21/9/03 19/2/0 3
			Dredge repairing; life-saving appliances in good order	13/8/03
*Alexandra Lead	Alexandra Lead Gold-dredging Com-	Robert Ross	Sleeve required on projecting end of main engine-shaft; well-hole fencing forward not up;	21/2/03 13/8/03
*Molyneux Hydraulic	Molyneux Hydraulic Gold-dredging	C. Simonsen	arter wen-note uncovered Well-hole railing down; guard on screen driving-gear not sufficient	21/2/03
*Alexandra Eureka	Olinpany Alexandra Eureka Gold - dredging	N. Bradley		13/8/03 19/2/03
*New Golden Beach	Company New Golden Beach Gold-dredging	Charles B. Curno	Dredge idle	15/8/0 3 19/2/03
	Company		Dredge undergoing extensive alterations	15/5/03
,		T. Bringam	Dredge still undergoing extensive alterations	15/8/03
*Ngapara No. 1	Ngapara Gold-dredging Company	M. G. Scott	Dredge and life-saving appliances in good order	20/2/03
*Ngapara Extended	Ngapara Extended Gold-dredging	G. McDonald		20/2/03
*Enterprise No. 1	Company Enterprise Gold-dredging Company	S. J. Luke	New copy of regulations required; two lifebelts to be renewed	$ \frac{13/8/03}{20/2/03}$
*Enterprise No. 2		G. R. McGregor	Rails not in position at stern, round well-holes and across tables Dredge and life-saving appliances in good order	17/9/03
Earnscleugh No. 3	Earnscleugh Gold-dredging Company	C. Weaver	Life-saving appliances not yet complete	17/9/03 6/3/03
			Several guards required about the elevator, screen, and silt-elevator driving gear; also guard-rails required about all the top gear: these requirements were nointed out	22/9/03
*Earnseleugh No. 1 *Earnseleugh No. 2	, ,	J. Fouhy	Well-hole gangway and fencing required; regulations defaced	15/8/03 15/8/03
		a British		