DIGESTERS found to be defective on Inspection during Financial Year ended the 31st March, 1907.

Description of Defects.					Dangerous.	Defective n Lesser Degree.	Total.
A number of rivets bad		•••	•••			8	8
All rivets in circumferents	ial and l	ongitudi	inal seam	s, top	4	•••	4
Bolts in doors defective		•••			•••	5	5
Bolts in mouthpiece wast	ed					2	<b>2</b>
Circumferential seams wa		•••			•••	3	3
Door defective					1		1
Eighty-seven bad rivets	•••	•••				1	1
						1	1
T3 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4						1	1
Frame of bottom door, jos	int defec	tive				1	1
General deterioration (pressure reduced)						5	5
Landings wasted	•••			\		4	4
Ninety rivets defective				{		1	1
One hundred rivets defect	tive					1	1
One hundred and fifty riv					2		<b>2</b>
Pins in longitudinal stays						1	1
Several rivets bad	•••					3	3
Top door defective		<b></b>				1	1
Twenty defective rivets					• • •	1	1
Vertical stays wasted	•••		• • •		•••	2	2
Totals	•••	•••	•••		7	41	48

DEFECTIVE FITTINGS found on Inspection of Boilers for which Notice was given to renew or repair during Financial Year ended the 31st March, 1907

- 1 Bend of main steam-pipe bad: has been  ${f renewed}.$
- 16 Blow-off cocks bad: have been renewed.
- 10 Blow-off cocks defective: have been repaired.
- Blow-off cock fitted with new bolts.
- 5 Blow-off cocks rejointed, and new studs fitted in boiler.
- 5 Blow-off pipes bad: have been renewed.
- 1 Bracket-bolts, brake-nut, and steering-gear worm of traction-engine renewed.
- 1 Cog-wheel of brick-machine loose: was made secure.
- Crank-pin of engine defective: was renewed.
- 1 Crank-shaft saddle on boiler rejointed.
- 2 Crank-shafts fractured: have been renewed.
- Cylinder cracked: was repaired.
   Cylinder drain-cocks broken: new ones fitted.
- Digester door bad: new one fitted.
- 2 Feed check-valve chests and valves bad: were renewed.
- 1 Feed check-valve chest rejointed and new studs fitted.
- 1 Feed-pump defective: has been repaired.
- Feed check-valve chest bad: was renewed.
- 8 Feed-pipes defective: have been renewed. 60 Ferrules fitted under spring-balance levers.
- 1 Flange of blow-off cock defective: was re-
- 1 Fly-wheel defective: was repaired.
- Fly-wheel of engine cracked: new one fitted.
- 1 Fly-wheel bracket on boiler loose: was made
- Friction-wheel defective: has been renewed.
- 20 Fusible plugs defective: have been renewed.
- 1 Girder for hanging boiler fitted.
- Governor out of order: made workable.
- Injector out of order: made workable.
- 2 Internal feed-pipes defective: have been repaired.

  2 Main steam-pipes bad: have been renewed.
- Main steam-pipe defective: was repaired.
- 4 Main steam pipes requiring supports: hangers fitted.
- 10 Manhole-doors bad: have been renewed.
- Manhole-door dog bad: has been renewed.
- 2 Manhole-door studs bad: were renewed.
- 30 Mudhole-doors bad: have been renewed. Mudhole-door studs bad: have been renewed.
- 1 New bolts fitted to blow-off cocks.

- 1 New bolts fitted to steam-pipe joint.
- 1 New feather fitted in stearing-gear worm for traction-engine.
- New handles fitted to water-gauge cocks.
- New jaw for safety-valve lever fitted.
- 1 New nipple fitted to check-valve chest.
- 1 New nut and screw fitted to brake for traction-engine.
- New seat fitted in stop-valve chest.
- New stud fitted to end of blow-off cock.
- Pipes for blow-off cocks bad: have been re-
- Safety-valves bad: have been renewed.
- Safety-valves defective: were repaired.
- Safety-valves rejointed and adjusted.
- Safety-valve seat defective: was renewed.
- Safety-valve chests, joints leaking: were re-
- 10 Spring-balances bad : have been renewed.
- Spring-balance defective: was repaired.
- 61 Steam-pressure gauges bad: have been re-
- 2 Steam-pressure gauge-pipes bad: were renewed.
- 3 Steam and water gauge fittings defective: were repaired.
- 3 Steering-gear for traction-engines defective: was put in working-order.
- 1 Spoke of fly-wheel cracked, clamp fitted to it.
- 5 Springs for safety-valve wasted: have been renewed.
- Stop-valve defective: has been repaired.
- 1 Stop-valve refaced.
- 1 Stop-valve joint defective: has been remade.
- 1 Stop-valve bad: has been renewed.
- Stop-valve gland fitted with new bolts. Stud in blow-off cock joint bad: was re-
- Syphons for pressure-gauges, renewed. Tapered mud-plugs defective: have been 13 renewed.
- Test-cocks defective: have been repaired.
- Test-cocks bad: have been renewed.
- Throttle-valve defective: was repaired.
- Washer and stud bottom of blow-off cock renewed.
- 53 Water gauge mountings defective: have been repaired.
- 35 Water-gauge mountings bad: were renewed.