

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
7	Multitubular	Manhole-doors repaired.
5	"	Mudhole-doors repaired.
3	"	New bottom-plates fitted in shell.
1	"	New compensating-ring fitted round manhole-opening, and new door fitted.
2	"	New flanged riveted plates fitted to bottom of steam-dome.
9	"	New manhole-doors fitted.
15	"	New mudhole-doors fitted.
1	"	Nineteen new tubes fitted.
4	"	One new longitudinal stay fitted.
3	"	Patches fitted on bottom of shell.
2	"	Patches fitted on front tube-plate.
1	"	Patch fitted on crown of steam-dome, and manhole-door repaired.
1	"	Patch fitted on crown of steam-dome, and riveted washer under stay-nut.
1	"	Patch on top of boiler renewed.
4	"	Retubed.
1	"	Retubed, and new tube-plate fitted.
2	"	Several new rivets put in shell.
11	"	Several new tubes fitted.
1	"	Supporting girder fitted over top of boiler.
1	"	Two new longitudinal stays fitted.
1	"	Two rows of tubes renewed.
11	Portable	A number of new screwed stays fitted in firebox.
3	"	A number of new tubes fitted.
1	"	All new screwed stays fitted in firebox, six new stays from crown of boiler to crown of firebox, patch fitted in firebox, compensating-rings round mudhole-openings, and four sight-holes cut and plugs fitted.
1	"	Compensating-rings fitted to manhole and mudhole openings, seventeen new screwed stays fitted in firebox, and patches fitted to bottom corners of firebox.
2	"	Compensating-rings fitted to manhole-openings.
34	"	Compensating-rings fitted to mudhole-openings.
1	"	Corner of firebox patched, eighteen new screwed stays fitted in firebox, and patch on shell under blow-off cock.
1	"	Fifteen new screwed stays fitted in firebox, and an additional dog-stay on crown of firebox.
3	"	Foundation-rings repaired.
1	"	New dog and stud fitted to mud-door.
1	"	New firebox-crown fitted.
1	"	New firebox fitted, lower part of front plate renewed, patches fitted on side of firebox and throat-plate, new foundation-ring, all new tubes, and two new girder-stays.
1	"	New manhole-door fitted.
6	"	New mudhole-doors fitted.
2	"	One new longitudinal stay fitted.
5	"	Patches fitted in firebox.
8	"	Patches fitted on tube-plates.
1	"	Patch fitted on outer shell of firebox.
1	"	Patch fitted on shell of boiler under blow-off cock, and three new sighting-plugs fitted.
5	"	Patches in firebox renewed.
12	"	Retubed.
2	"	Retubed, and new tube-plates fitted.
1	"	Retubed, and two extra dog-stays fitted on crown of firebox.
1	"	Retubed, and two new longitudinal stays fitted, also seventeen new screwed stays in firebox.
1	"	Retubed, and two patches fitted on front of outer shell of firebox.
19	"	Several new screwed stays fitted in firebox.
4	"	Several new tubes fitted.
1	"	Six new tubes fitted, and shell patched under cylinders.
2	"	Studs renewed in mudhole-doors.
2	"	Tapered plug-holes cut, and plugs fitted.
1	"	Thirty new screwed stays fitted in firebox, and patch fitted on shell under feed-pump chest.
1	"	Three new longitudinal stays fitted.
1	"	Two new longitudinal stays fitted.