
Fig. No. 8.



Measuring-stand.

- A. Littlejohn's brass chain grip, with swivel loop.
 B. Slow-motion screw.
 C. Gun-metal adjustable frame, with slow-motion screw.
 D. Weight.