DEFECTIVE FITTINGS FOUND ON INSPECTION OF BOILERS FOR WHICH NOTICE WAS GIVEN TO REPAIR DURING THE FINANCIAL YEAR ENDED THE 31ST MARCH, 1912.

- 1 Bend of feed-pipe defective: has been renewed.
- 1 Bends of main steam-pipes bad: have been renewed.
- 10 Blow-off cocks bad: have been renewed.
- 5 Blow-off cocks defective: have been repaired.
- 6 Blow-off pipes bad: have been renewed.
- Crank shafts of engine fractured: were renewed.
- 2 Cylinders rejointed to boiler.
- 2 Cylinders renewed, and pistons fitted with new rings.
- Defective clutch on shaft renewed.
- 2 Feed check-valve chest defective: was renewed.
- 4 Feed check-valves defective: were renewed.
- 2 Feed-pipes bad: were renewed.
- 2 Feed-pumps defective: have been repaired.
- Ferrules fitted under spring-balance safetyvalve levers.
- Flywheel of engine cracked: was renewed.
- 18 Fusible plugs defective: were renewed.
- 2 Governors defective: were put in order.
- 2 Injectors found defective: were renewed.
- 1 Main steam-pipe bad: was renewed.
- 1 Main steam-pipe defective: was repaired.
- 14 Manhole-doors bad: have been renewed.
- 3 Manhole-door studs bad: were renewed.
- 37 Mudhole-doors bad: have been renewed.
- 5 Mudhole-door studs bad: have been renewed.
- 1 New brake fitted to traction-engine.

Total

- 1 New cylinder fitted to engine.
- New stop-valve for injector fitted.
- New studs fitted in safety-valve chests.
- Safety-valves bad: have been renewed.
- Safety-valve chests defective: have been renewed.
- 17 Safety-valves defective: were repaired.
- Safety-valve levers cut to correct length.
- 28 Steam-pressure gauges bad: have been renewed.
- 2 Steam-pressure gauge-pipes defective: were renewed.
- Steam stop-valves bad: were renewed.
- Steam stop-valves refaced.
- 2 Syphon-pipes for steam-pressure gauges renewed.
- Tapered mud-plugs defective: have been renewed.
- Tapered sight-plugs defective: have been renewed.
- 14 Test-cocks bad: have been renewed.
- 3 Test-cocks defective: were repaired.
- Traction-engine brakes repaired.
- Traction-engines' steering-gear defective: was put in order.
- Traction-engines' steering-gear worm renewed.
- Water-gauge-glass protectors fitted.
- 20 Water-gauge mountings bad: have been renewed.
- 5 Water-gauge mountings defective: were repaired.
 - .. 280

No. 3.—Return of Notices given to repair Boilers during the Financial Year ended the 31st March, 1912.

Number.	Туре.	Description of Repairs.
1	Cornish	Bosom-piece fitted round flanging of furnace-front.
ī		The share also are sined
î	,,	Charled martin of furnace aroun out out and notab fitted
1	,,	Turne and annual could be
. 1	,,	Connect atoms sominated
ī	,,	Patch fitted on back end of furnace.
$\bar{1}$,,	Small crack in furnace repaired.
1	,,	Two stays fitted between crown of boiler and furnace where furnace- crown down.
1	,,	Two stays renewed.
1	Cornish tubular .	1 7 64 7
2	,,	0
2	,,	Databas non arrad
1	,,	Retubed, and new back tube-plate fitted.
1	,,	Two notehos fitted areas grown on bettern of boiles and one tube
1	,,	
1	Cornish vertical .	New angle-ring fitted at top end of flue.
1	,,	
1	Dryback marine .	
1	,,,	Seams on bottom of shell caulked.
1	Lancashire .	
1	,,,	
2	,,,	
1	,,	
3	Locomotive .	
1	,,, .	All sling stays renewed, and four new screwed stays fitted in firebox.