No. 3.—RETURN OF NOTICES GIVEN TO REPAIR BOILERS—continued.

Number.	Туре.		Description of Repairs.
1	Multitubular		Retubed, and new longitudinal stays fitted.
î	,,		Retubed, and twenty rivets renewed in shell.
5	,,,	• •	Several new tubes fitted.
1	,,		Several rivets in gusset-stays renewed.
1	,,		Small patch fitted under bottom of shell.
2	,,		Steam-dome repaired.
. 1	,,		Steam-dome, several rivets renewed.
1	,,		Ten new tubes fitted.
1	,,	• •	Thirteen tubes renewed.
1	,,	• •	Top of back tube-plate patched.
1	,,	• •	Two new longitudinal stays fitted
$rac{1}{1}$,,	• •	Two new longitudinal stays fitted. Two new stay-tubes, and forty rivets renewed.
1	,,	• •	Two patches fitted on shell.
4	Portable	• •	A number of new screwed stays fitted in sides of firebox.
1		• • •	All crown-stays in firebox renewed.
î .	,,		Bottom of firebox patched.
$1\overline{2}$,,,		Compensating-rings fitted to mudhole-openings.
2	,,		Compensating-rings fitted to mudhole-openings, and patch in firebox.
2	,,	• •	Compensating-rings fitted to mudhole-openings, and new studs in doors.
1	,,		Crown girder-stays renewed.
1	33		Crown of firebox cut out where cracked, and patch fitted.
2	,,		Crown of firebox repaired.
3	,,,		Defective patches taken off and larger ones fitted.
1	,,		Eight new screwed stays fitted in firebox.
1	,,		Eighteen new screwed stays fitted in firebox.
1	٠,,	• •	Extra girders fitted on crown of firebox where bulged.
$\frac{2}{1}$,,	• •	Firebox-crowns renewed.
1	,,	• •	Five new screwed stays fitted in each side of firebox.
1	,,	• •	Five new screwed stays fitted in throat-plate.
1	"	• •	Five new tubes fitted.
$\frac{1}{1}$,,		Four longitudinal stays renewed. Four mudhole-openings fitted with compensating-rings.
1	"	• •	Fourteen new screwed stays fitted in firebox.
1	"	• •	New firebox fitted.
1	"		New fire-door ring fitted, and plate renewed.
i	33	• •	New girders fitted on crown of firebox.
ĩ	"		New manhole-doors fitted.
2	"		New manhole-doors fitted, and compensating-rings reriveted.
4	Portable		New mudhole-doors fitted.
1	,,		New mudhole-door fitted, and compensating-ring renewed.
1	,,		New stud and dog fitted to mud-door.
1	,,		One new longitudinal stay fitted.
1	,,	• •	Patch at corner of foundation-ring renewed.
3	,,	• •	Patches fitted in firebox.
2	,,	••	Patches fitted in firebox, and compensating-rings fitted to mudhole-
		Ì	openings.
$\frac{2}{2}$	**	• •	Patches fitted in firebox, and several new screwed stays.
$\frac{2}{2}$,,	•••	Patches fitted on tube-plate.
$egin{array}{cccc} 2 & & & \\ 6 & & & \end{array}$	**	•••	Patches fitted on shell of boiler under mountings.
ь 1	,,	• • •	Retubed. Retubed, and new firebox fitted.
1	,,	••	Retubed, and new longitudinal stays fitted.
1	"	• •	Retubed, and new toberplate fitted.
5	,,		Several new screwed stays fitted in firebox.
2	,,		Several new screwed stays fitted in firebox, and compensating-rings
-	,,	.	to mudhole-openings.
1	,,		Strengthening stays fitted to crown of firebox.
î	,, ,,		Ten new screwed stays fitted in firebox.
1	,,		Thirteen new screwed stays fitted in firebox.
1	,,		Thirty new screwed stays fitted in firebox.
1	,,		Three new girders and stays fitted on firebox crown.
1	,,		Three new tubes fitted.
1	,,		Twenty new screwed stays fitted in firebox.
1	,,		Twenty-seven new screwed stays fitted in firebox.
1	,,		Twenty-two new screwed stays fitted in firebox.