RETURN OF WRECKS AND CASUALTIES TO SHIPPING REPORTED TO THE MARINE DEPARTMENT, ETC.—continued.

	_	.0.	N. III	Vinnshor of	No.	Nature of	View hor		1111	n :		
Vessel's Name,	E	ete gar	H N	noer or	Nat		of of	Place where	M	Wind.	Tito Since of Count of Locusius	Nome of Macter
Class.	Sara!	igeA inoT	.мөтО	Passen- gers.	Cargo.	Casualty.	Lives lost.	Casualty occurred.	Direc- tion.	Force.	r maing of Court of Inquiry.	Name of Masuer.
Himitangi, s.s 16 years	Schooner	149	16	56	General	Triffing accident to machinery	:	At sea between Chatham Islands and	N.W.	Strong	Steam-pipe burst owing to flaw in copper	C. Thompson.
Waimate, s.s., 19 years	Schooner	3,629	96	:	General	Damage by heavy seas	:	Lytreron South Indian Ocean	S.W.	Gale	The ship encountered very stormy weather for three days and shipped heavy seas. which did considerable damage to ship and	G. F. Mead.
Otaki, s.s., 7 years	Schooner	4,611	62	:	General	Damage by heavy seas	:	South Indian Ocean	S.W. and N.W.	Gale	The ship experienced very heavy gales, rising to hurricane force, and shipped heavy seas, which carried away the deck cargo. Very little downway and the chiral states and the chiral states.	A. B. Smith.
S p a rrowhawk, s.s., 3 years			4	:	Vehicles	Collision; tri-		Anal-land Harban	B	Light	ntitle damage was done to the suip	C. Williams.
Eagle, p.s.	Ferry-boat	138	ग	 9:	:	Collision; tri-	:	Auchiallu marbour	· •	ः भाक्षान	THE ASSESS CONTINUE IN METERS OF SECTION AND THE	C. Poole.
Corinna, s.s., 33 years	Schooner	. 81	30	•	General	Stranded; damage, £500	:	Barrett's Reef, Welling- ton Heads	zi	Light	The master did not take proper precautions to see that the vessel was kept on her proper course within the white sector of Some's Island light. His certificate was suspended for three months, and he was ordered to pay the coats of the inquire.	D. Cameron.
:	Cutter	9	-	6/1	Explosives	Explosion of keg of powder; damage, £75	-	King's Wharf, Auckland	•	:	The cause of the explosion, which fatally injured the mester, is not known, but was probably due to carelessness on the part of those on board, who were snoking and were mader the influence of linner	W. R. Huff.
Riverina, s.s., 10 years	Schooner 2,808	2,808	86	87	General	Broken piston		Lat. 33° 53′ S., long. 153° E.	•	:	The H.P. piston-rod ran hot, and the H.P. engine was disconnected and the trip continued with the ordinary continu	G. F. Entwistle.
Endeavour, aux.,11 years	Schooner	70	4		Coke	Stranded; slight damage	:	Orewa Beach, Auck- land	N.W.	Calm	The master set the course and left the ressel in charge of William Sutcliffe, A.B. who altered the course without authority, and also failed to call the master, as instructed.	A. E. Ragg.
Riverina, s.s., 10	Schooner	2,808	66	7	General	Slight accident	:	25 miles from Godley	:	Calm	and consequently ran the vessel ashore The intermediate slide-spindle broke	G. F. Entwistle.
Squall, s.s., 11	Schooner	145	14	:	Cement	Broken pro-	:	Cook Strait	N.W.	Light	Struck a submerged object, presumably a	R. Fletcher.
years Waihora, s.s., 7 years	Schooner	2,993	41	•	:	Stranded; no	:	Off Pouto Point, Kai- para	z <u>i</u>	Gale	Indexing 10g The vessel was steering a course with the sun right ahead, and the red buoy marking the channel was not distinguished in the bright sunshine until it was too late to avoid run.	A. C. Showman
Clutha, p.s., 4 years	•	96	9	•	General	Stranded; n o damage	:	Mouth of Tuapeka River	:	Calm	ning on to a sandbank A valve had been left open, and as the vessel was filling with water she was beached to avoid sinking	K. Tsukigawa.