



NO. 7.—FRACTURES OF CONDUCTORS 5 FT. 8 IN. FROM I BEARER END OF CABLE BREAK.



NO. 8.—ARMOUR WELDED WITH $\frac{1}{8}$ IN. OVERLAP AND CLAIMED TO HAVE BEEN WELDED TO I BEARER.