

July	16	Taupo, s.s., 15 years	408	22	..	Coal and timber	Stranded; total loss	..	Outside North Tip Head, Greymouth	Vessel broke away from her moorings at the wharf during heavy fresh in river, and, drifting out to sea, stranded outside North Tip Head. Casualty caused through the windlass breaking. No blame attached to master, officers, or crew	Charles Brophy.
"	30	Douglas, s.s., 18 years	60	5	4	Coal	Stranded; total loss	S.W.	North Spit, Moka River	Light	..	Heavy sea broke on board while attempting to cross bar off Moka River, and water getting into the stokehold and engine-room lowered steam-pressure from 70 lb. to 50 lb., and rendered her unable to contend against seas rolling in. A coir tow rope washed overboard, also fouled the propeller. No blame to any one on board	Alfred Jones.
Aug.	3	Lark, 19 years	139	8	..	Timber	Stranded; partial loss	N.E.	Abreast Heads Anchorage, Kaipara Harbour	Moderate breeze	..	When getting under weigh the vessel did not wear as smartly as anticipated, and when nearing the beach-side of channel the anchor, which was not hove high enough, caught the ground, and the ebb tide shot the vessel up the beach	Niel McDonald.
"	17	Falcon, 23 years	98	6	..	Timber	Stranded; partial loss	N.W.	About 150 yards from north side of entrance to Timaru Harbour	Strong breeze	..	Casualty caused through vessel not answering her helm, or helm not being put hard a-starboard by man at the wheel when the order was given	Edward Petersen.
"	23	Mapourika, s.s., 2 years	718	44	22	General	Stranded; partial loss	..	Mabel Island, off Picton, Queen Charlotte Sound	Calm	..	Casualty solely attributable to error of judgment on part of second officer in keeping too far to the westward after passing the snout, having been deceived by the shadow. All certificates returned, and costs of inquiry, £2 14s., ordered to be paid by second officer, Frederick William Baron	David Spence.
Sept.	6	Tararawa, 15 years	44	3	..	Ballast	Loss of life only	S.W.	One mile S.W. of Tiri Tiri Light, Hauraki Gulf	The master fell overboard while intoxicated, and was drowned	John Nelson.
"	14	Hermione, 23 years	1120	23	..	General	Loss of life only	N.E.	Nine miles south of Chasland's Mistake, Foveaux Straits	Fresh breeze	..	An A.B., Daniel Bowen, fell from the upper foretop-sail-yard to the deck, and was killed instantaneously	John James Alsop.
"	25	Rock Lily, 13 years	50	4	..	Timber	Stranded; slight damage	E.	Bar of Waimakariri River	Moderate breeze	..	Casualty caused through shifting bar. Vessel touched and lost way, and then grounded out of channel	William T. Taylor.
"	29	Glencairn, 15 years	62	5	..	Timber	Stranded; total loss	S.S.E.	Opposite Lake Ellesmere, Ninety-mile Beach	Storm	..	Casualty caused by stress of weather. Master did everything he could to save vessel, and showed great judgment in beaching her as he did, thereby saving lives of his crew	Charles Watchlin.
Oct.	2	Lord of the Isles, 19 years	208	8	..	Bonedust and coal	Stranded; total loss	S.W.	North side of Northern Sandspit, entrance to Kaipara Harbour	Fresh breeze	..	Master held responsible for wreck of vessel, and ordered to pay £8 14s., costs of inquiry	Robert Armit.
"	21	Linda Weber, 23 years	114	7	..	Coal	Stranded; partial loss	S.S.E.	Two miles north of East Cape	Fresh gale	..	Vessel touched shallow sunken patch, causing hole in her bottom, and, as water gained on pumps, master decided to run into Hicks Bay, and beach vessel	Simon McKenzie.
"	24	Gertie, s.s., 9 years	119	14	..	Coal	Stranded; partial loss	W.N.W.	Bar of Waitara River	Fresh	..	Casualty caused through heavy sea striking vessel on bar, causing her to touch ground, and lose steering-way	George Archibald Simpson.
"	25	Rosamond, s.s., 16 years	462	20	..	Timber	Collision; partial loss	S.W.	Wharf No. 7, Lyttelton	Strong breeze	..	Vessel ran stern on to pile-head of wharf; sternway not checked in time	Alexander Sutherland.