


— Mines Department. —
— NEW ZEALAND. —



— PLAN —
— OF THE —
— **WELCOME GROUP OF MINES.** —
INANGAHUA GOLDFIELD.
— **NEW ZEALAND.** —
SHOWING PRINCIPAL MINING LEASES & WORKINGS.

— 1909. —

Compiled from Official Plans
by Julius Schadick, Licd Surveyor & C.E.

— Scale of Chains. —

