Table 20--Defects Found in Goods-service Vehicles on the Basis of 100 Vehicles Examined

	D. C. d				Vehicles Licensed Under Transport	Ancillary Vehicles.	
	Defect.					First Inspection.	Second Inspection
Unladen weight displa	ved				19.6	36.1	18.2
Trade name and addre	SS				11.4	$35 \cdot 6$	16.9
Headlights					32.5	29.8	$30 \cdot 6$
Tail-lights and marker	lights				29.6	$15 \cdot 7$	25.8
Warning-device					6.9	$4 \cdot 2$	3.1
Windscreen-wiper					6.2	$5 \cdot 7$	3.8
Rear-vision mirror	, .				11.4	16.8	9.8
Tires					$2 \cdot 2$	$3 \cdot 2$	$1 \cdot 2$
Suitable jack carried					1.6	$3 \cdot 0$	2.0
Fuel-supply safe					2.0	$2 \cdot 0$	1.0
Brake connections					17.0	$55 \cdot 9$	21.5
Steering-gear					55.4	$43 \cdot 7$	$44 \cdot 2$
Transmission, springs,	and sha	$_{ m ickles}$			24.0	$14 \cdot 2$	$17 \cdot 2$
Engine condition					9.5		$7 \cdot 2$
Cab and body condition	n					21.8	$21 \cdot 1$
Driver's exit					26.9		
Body suitably partition	ned				$1 \cdot 3$	3.0	1.4
Over-all dimensions, 39) ft.				0.6		0.4
Brakes, foot, at 20 m.;					19.0	17.8	$23 \cdot 2$
Brakes, hand, at 20 m	p.h.				25.5	$19 \cdot 7$	$26 \cdot 7$
Free of defects					35.7	$5 \cdot 7$	16.7

Table 21—Defects in Private Cars, etc., on the Basis of 100 Vehicles Examined*

	Item.	Number of Defects Per 100 Vehicles Examined.		
Brakes, foot		 	23.2	
Brakes, hand		 	$22 \cdot 4$	
Lights, head		 	19.0	
Lights, tail		 	4.5	
Steering-gear		 	18.2	
Windscreen-wiper		 	$1 \cdot 7$	
Rear-vision mirror		 	0.3	
Warning-device		 	1.1	
Door-fastenings		 	$2 \cdot 1$	
Vehicles free from de	$_{ m efects}$	 	$51 \cdot 3$	

^{*} The defects relate to the last inspection (carried out by the municipal testing-stations at Wanganui, Christehureh, and Dunedin) prior to 31st March, 1950.