

RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Semi-tubular	... New sludge-door.
1	"	... Several stays renewed.
1	"	... Furnace-crown strengthened.
2	Traction	... New tubes and firebox fitted.
1	"	... Patches in firebox and on outside shell renewed, also tube-ends cut off and beaded over.
1	"	... Two patches in firebox and four new stays.
2	"	... A number of new screwed stays fitted in firebox.
6	"	... A number of new tubes put in.
1	"	... Patch fitted on shell under blow-off cock.
3	"	... Fireboxes patched.
13	"	... Retubed.
1	"	... New firebox and new screwed stays fitted.
1	"	... Seven new screwed stays fitted in firebox.
1	"	... Seven new tubes put in.
1	"	... New pins put in end of palm-stays.
4	"	... Compensating-rings fitted round sludge-door openings.
1	"	... Patch put on back head.
1	"	... Twenty new screwed stays put in firebox.
1	"	... New studs and nuts for manhole-door.
1	"	... Compensating-ring fitted round manhole-opening and four new stay-tubes.
1	"	... Old patch taken off firebox and a larger one fitted.
1	"	... Eight new screwed stays in firebox.
1	"	... Eleven new screwed stays in firebox.
5	"	... Tubes expanded and ferrules fitted.
3	"	... A number of tubes drawn for cleaning and replaced.
1	Vertical cross tube	... Lower half of shell renewed.
1	"	... Patch put on shell under feed-pump.
1	"	... New uptake fitted.
1	"	... Patch fitted under blow-off cock.
1	"	... Foundation renewed.
1	"	... Compensating-ring round sludge-door opening, and two patches at bottom of shell.
1	"	... Manhole-door repaired.
1	"	... New sludge-door fitted.
1	Vertical flue	... One new stay fitted.
1	"	... Compensating-ring fitted round sludge-door opening and check-valve opening.
1	"	... Patch round skirting of firebox.
1	"	... New firebox-crown and new uptake.
2	"	... New uptakes fitted.
1	"	... Compensating-ring round sludge-door opening, also round water-gauge openings.
4	"	... New sludge-doors fitted.
1	"	... Nine extra stays put in furnace.
1	"	... Compensating-ring round sludge-door opening and uptake re-riveted.
2	"	... Uptake patched.
1	"	... Lower half of shell renewed, new neck-piece round uptake, new furnace-crown, six new stays, and patch at bottom of firebox.
1	Vertical field tube	... Retubed.
1	"	... New sludge-door.
1	"	... Compensating-ring round sludge-door openings.
1	Vertical portable	... New sludge-door.
1	"	... Compensating-rings round sludge-door openings.
12	Vertical tubular	... "
15	"	... Retubed.
1	"	... Four new stays fitted.
1	"	... New firebox-crown.
1	"	... Two new stays fitted.
1	"	... New crown-plate fitted.
1	"	... Firebox patched.
1	"	... Patched round line of firebars.
2	"	... New stays fitted.
8	"	... New crown and new tubes fitted.
1	"	... New set of tubes and four new stays.
4	"	... New sludge-hole doors.
1	"	... Three new stays put in.
1	"	... New top tube-plate.
1	"	... A number of new tubes.