

No. 3.—RETURN OF NOTICES given to REPAIR BOILERS—*continued*.

Number.	Type.	Description of Repairs.
1	Portable	... Retubed, and two new longitudinal stays.
1	"	... Retubed, and firebox patched.
1	"	... Retubed, new firebox-crown, and three new longitudinal stays.
1	"	... Rivets in front tube-plate renewed.
4	"	... Six new screwed stays in firebox.
1	"	... Six new stay-tubes.
1	"	... Six new tubes and firebox patched.
1	"	... Six new screwed stays in firebox, and compensating-ring fitted to manhole-opening.
1	"	... Sixteen new tubes.
1	"	... Ten new screwed stays in firebox.
1	"	... Ten new screwed stays in firebox, mudhole cut and new door fitted, also sight-plug fitted.
1	"	... The crown of boiler under cylinder, where bad, cut out and new plate fitted.
1	"	... Three new longitudinal stays, and compensating-rings fitted to mudhole-openings.
1	"	... Three new tubes, and new mud-door.
1	"	... Three new longitudinal stays, and three new screwed stays in firebox.
1	"	... Two new longitudinal stays fitted.
1	"	... Tubes beaded in front tube-plate.
1	"	... Tubes drawn and barrel cleaned.
1	"	... Two new longitudinal stays, compensating-rings round mudhole-openings, and new mud-doors.
3	"	... Two new screwed stays in firebox.
1	"	... Twenty new screwed stays in firebox.
1	"	... Twelve new rivets in shell, and one new longitudinal stay.
1	"	... Upper row of tubes renewed.
1	Semi-portable	... Compensating-rings fitted round mudhole-openings, and two new mud-doors.
1	"	... Corners of firebox patched.
1	Semi-tubular	... A number of tubes renewed.
1	"	... Defective rivets in patch in furnace renewed.
1	"	... Laminated portion of plate cut out of furnace, and patch fitted.
1	"	... Piece cut out of left-hand furnace where defective, and patch fitted; also strengthening-ring fitted to furnace.
1	"	... Patch fitted under bottom of boiler.
6	"	... Retubed.
1	"	... Retubed, and crack in tube-plate chain-pinned.
1	"	... Side seams recaulked.
3	"	... Tubes drawn and tube-plates cleaned.
1	Traction	... All screwed stays in firebox renewed.
1	"	... Compensating-rings fitted to mudhole-openings.
1	"	... Five new stays on crown of firebox.
1	"	... Fifteen new tubes.
1	"	... Four new tubes.
1	"	... Four new tubes and new mud-plugs.
1	"	... Front tube-plate renewed.
4	"	... New firebox fitted.
1	"	... New girders on crown of firebox, and two new studs in manhole-door.
1	"	... New stay-tubes fitted.
1	"	... New studs in manhole-door.
1	"	... Nineteen new screwed stays in firebox.
1	"	... Patches fitted to each side of firebox, one side taking four screwed stays, the other six.
1	"	... Patch fitted on back head under blow-off cock.
2	"	... Patches fitted on crown of firebox.
1	"	... Plughole in front tube-plate retapped and new tapered plug fitted.
9	"	... Retubed.
1	"	... Retubed, new firebox, new screwed stays in firebox, and four stay-tubes fitted.
1	"	... Seven new tubes.
1	"	... Sides of firebox patched.
1	"	... Ten new tubes.
1	"	... Three new tubes.
1	"	... Three new screwed stays in firebox.