




Diagram shewing 4th. Point check on 400th. Low Water, Auckland 1913.